

QTouch Design Guide

Atmel provides a QTouch library for the design of capacitive sensors using the QTouch technology. Implementation in Atmel Studio requires downloading QTouch libraries from the Atmel website. This enables the user to create a QTouch Executable Project in Atmel Studio 6 and use the built-in library functions. Following is the link to register and download the [QTouch Library 5.0](#)

The basic algorithm for designing a QTouch based sensor is :

- 1) Configure sensors as keys/rotors/sliders using :


```
void qt_enable_key (channel_t channel, aks_group_t aks_group, threshold_t detect_threshold, hysteresis_t detect_hysteresis)
void qt_enable_rotor (channel_t from_channel, channel_t to_channel, aks_group_t aks_group, threshold_t detect_threshold, hysteresis_t detect_hysteresis, resolution_t angle_resolution, uint8_t angle_hysteresis)
void qt_enable_slider (channel_t from_channel, channel_t to_channel, aks_group_t aks_group, threshold_t detect_threshold, hysteresis_t detect_hysteresis, resolution_t position_resolution, uint8_t position_hysteresis)
```
- 2) Set the touch parameters for the library – like the threshold level, detect integration values that set the number of counts the signal level should differ from the reference level in order to be registered as a touch, Maximum ON duration etc.
- 3) Initialize sensing using *qt_init_sensing()* to calibrate the channels and prepare the sensors for capacitive touch. It is a library defined function.
- 4) Initialize the timer ISR to run periodically and determine the time for a capacitive measurement.
- 5) Repeatedly call *qt_measure_sensors()* for capacitive measurements and to update the status flags. Library data structure *qt_measure_sensors()* takes the current time in milliseconds as the parameter and updates 10 flags.
- 6) Check if repeated measurements are required (QTLIB_BURST_AGAIN flag set to 1). If required, then measure sensors again.
- 7) Check the *qt_touch_status[]* to see if any sensors are in detect. If yes, then perform desired action. Else, repeat from step 5.


qt_touch_status is a sub-field of the data structure *qt_touch_lib_measure_data_t*. The above data structure consists of three variables :

Fields	Type	Comment
channel_signals	uint16_t	The measured signal on each channel.
channel_references	uint16_t	The reference signal for each channel.
qt_touch_status	qt_touch_status_t	The state and position of the configured sensors

qt_touch_status is a variable of the data structure *qt_touch_status_t*.


Fields	Comment
sensor_states[]	For Sensor, the sensor_states. Bit "n" = state of nth sensor : Bit Value 0 - indicates the sensor is not in detect Bit Value 1 - indicates the sensor is in detect
rotor_slider_values[]	Rotors angles or slider positions if rotors and sliders are used. These values are valid when sensor states shows that the corresponding rotor or slider is in detect

The flow chart below is from the Atmel QTouch Library User Guide that gives a step-by-step approach to the design process.




VISUAL GUIDE WITH SCREENSHOTS :


Step 1 : In Atmel Studio 6, in the Start Page choose New Project. Create a GCC QTouch Executable Project and name it. Click OK. As an example, we named the project here LED_Blink.




Step 2 : Select the sensors you want to add in the project. The order in which the sensors are selected is important. The wizard allows a pin configuration only in increasing order. For example, a configuration of the sort Slider 0-2, Rotor 5-3 is not allowed. In this example, we chose 1 of each sensor. Select QTouch Technology and the device used. Click Next.




Step 3 : Select each sensor from the dropdown and assign a Sensor ID and define the size of each. The sensor ID assigned here will be used throughout to refer to the particular sensor.




For the Wheel and Slider, the orientation has to be selected in addition to the dimensions. In the example, a clockwise orientation is chosen for the Wheel and horizontal orientation with LeftToRight direction is chosen for the Slider.




The sensor IDs are chosen as 0 for button, 1 for the wheel and 2 for the Slider.



Step 4 : Next the ports used have to be selected. The SNSK port is connected to the series resistor and SNS port is connected through a capacitor to the series resistor. The sensors can be split over multiple ports (interport) or within the same port (intraport). Therefore, if the number of pins are sufficient, the SNSK and SNS ports can be one port. Some of the sensors can be moved to a new port pair SNSK2 and SNS2. In this case, we used port A as the SNSK1 and port B as the SNS. Click Next.




Step 5 : In this step, the exact Port pins have to be assigned to each sensor (as connected in hardware design). The pin numbers **HAVE** to be assigned in increasing order only. No sensor can have its channels connected to pins in decreasing order as mentioned before. However, it is not necessary that Port B pin 0 has to be connected to Port A pin 0; it can be any pin of A.



Step 6 : On clicking Next, the user is given an option to enable the debug interface and power optimization. The Debug interface enables the application to output measurement values to I/O pins, which can be used by a USB bridge to view the output on Hawkeye or QTouch Studio. It is disabled for this example.

The power optimization is used to reduce the power usage of the system by about 40%. However, this turns off the spread spectrum feature of QTouch, which is used for better electromagnetic compatibility. We disabled this feature in the example.



Step 7 : On clicking Next, a summary is generated. Click Finish. The wizard generates the code with separate files for setting up the timer, configuring the touch sensors, initializing the MCU system clock etc. There is also a main.c file that provides the user with an infinite loop to perform desired actions. The first step now is to configure the sensors using the function *config_sensors()* in the file LED_Blink.qtdgn → touch.c

The user can change the resolution of the slider/rotor from 8-bit to lower. The hysteresis can also be modified.

```

static void qt_set_parameters( void )
{
    /* This will be modified by the user to different values */
    qt_config_data.qt_di = 2;
    qt_config_data.qt_neg_drift_rate = 20;
    qt_config_data.qt_pos_drift_rate = 5;
    qt_config_data.qt_max_on_duration = 0;
    qt_config_data.qt_drift_hold_time = 20;
    qt_config_data.qt_recal_threshold = 1;
    qt_config_data.qt_pos_recal_delay = 0;
}

/*=====
Name : config_sensors -
Purpose : Configure the sensors
Input : n/a
Output : n/a
Notes : Generated code from QTouch Studio. Do not change
=====*/
static void config_sensors(void)
{
    qt_enable_key( CHANNEL_6, NO_AKS_GROUP, 10u, HYST_6_25 );
    qt_enable_rotor( CHANNEL_0, CHANNEL_2, NO_AKS_GROUP, 10u, HYST_6_25, RES_8_BIT, 0u );
    qt_enable_slider( CHANNEL_3, CHANNEL_3, NO_AKS_GROUP, 10u, HYST_6_25, RES_8_BIT, 0u );
}

```

Step 8 : The QTouch parameters can also be changed in the above file. The function *qt_set_parameters()* sets default values for the parameters. The user can change these values depending on the functionality and sensitivity desired. Refer to the end of this file for a description of what each parameter indicates.

Step 9 : The ISR is initialized in the function *init_timer_isr()* in src → QTouch → init_mcu_atmega1284.c

The timer is initialized to run at 50ms. This time can be changed if desired by the user depending on how often the touch measurement wants to be made.

```

/*=====
Name : init_timer_isr
Purpose : configure timer ISR to fire regularly
=====*/
void init_timer_isr( void )
{
    /* set timer compare value (how often timer ISR will fire) */
    OCR1A = ( TICKS_PER_MS * qt_measurement_period_msec );

    /* enable timer ISR */
    TMSK1 |= (1u << OCIE1A);

    /* timer prescaler = system clock / 8 */
    TCCR1B |= (1u << CS11);

    /* timer mode = CTC (count up to compare value, then reset) */
    TCCR1B |= (1u << WGM12);
}

ISR(TIMER1_COMPA_vect)
{
    /* set flag: it's time to measure touch */
    time_to_measure_touch = 1u;

    /* update the current time */
    current_time_ms_touch += qt_measurement_period_msec;
}

/*=====
Name : set timer period
=====*/

```

The user can change *qt_measurement_period_msec* macro defined as 50 in the above case to any value desired.

Step 10 : In *main.c*, the system is initialized by disabling the JTAG pins and prescaling the system clock (if desired). The file *qt_asm_tiny_mega.s* in *src* → *QTouch* does this using assembly language. Next the function defined for touch initialization *touch_init()* is called. This function sets up the Studio Masks which can be obtained from the QTouch studio by defining the pin configurations and type of sensors desired. It configures the sensors (*config_sensors()*), sets up the touch parameters with default values (*qt_set_parameters()*) and calibrates the sensors (*qt_init_sensing()*). The function for ISR initialization is also called. Now, the system is ready to measure data.

```

void touch_init( void )
{
    #ifdef QT_TOUCH_STUDIO_MASKS
    SNS_array[0][0]= 0x47;
    SNS_array[0][1]= 0x38;
    SNS_array[1][0]= 0x08;
    SNS_array[1][1]= 0x08;

    SNSK_array[0][0]= 0x47;
    SNSK_array[0][1]= 0x38;
    SNSK_array[1][0]= 0x08;
    SNSK_array[1][1]= 0x08;
    #endif

    /* Configure the Sensors as keys or Keys With Rotor/Sliders in this function */
    config_sensors();

    /* initialise touch sensing */
    qt_init_sensing();

    /* Set the parameters like recalibration threshold, Max_On_Duration etc in this function by the user */
    qt_set_parameters();

    /* Address to pass address of user functions */
    /* This function is called after the library has made capacitive measurements,
    * but before it has processed them. The user can use this hook to apply filter
    * functions to the measured signal values. (Possibly to fix sensor layout faults) */
    #ifdef _DEBUG_INTERFACE
    #ifdef _QDEBUG_TIME_STAMPS
    qt_filter_callback = &set_timestamp;
    #else
    #endif
    #endif
}

```

Step 11 : For measuring capacitive data, a function called *touch_measure()* is called in an infinite loop. This function checks the flag *time_to_measure_touch* which is set in the ISR every 50ms. Hence, it executes every 50ms and updates the status flags using the function *qt_measure_sensors()* and also updates the variable of the data structure *qt_touch_lib_measure_data_t*.

Step 12 : To check the status of the sensors and angle/position values, we define two macros as below :

```

#include <avr/io.h>
#include <avr/interrupt.h>
#define __delay_cycles(n) __builtin_avr_delay_cycles(n)
#define __enable_interrupt() sei()

#include "touch_api.h"
#include "touch.h"

/*-----
manifest constants
-----*/

/*-----
macros
-----*/

#define GET_SENSOR_STATE(SENSOR_NUMBER) qt_measure_data.qt_touch_status.sensor_states[(SENSOR_NUMBER/8)] & (1 << (SENSOR_NUMBER % 8))
#define GET_ROTOR_SLIDER_POSITION(ROTOR_SLIDER_NUMBER) qt_measure_data.qt_touch_status.rotor_slider_values[ROTOR_SLIDER_NUMBER] |

/*-----
type definitions
-----*/

/*-----
prototypes
-----*/
extern void touch_measure();
extern void touch_init( void );
extern void init_system( void );
extern void init_timer_isr(void);
extern void set_timer_period(uint16_t);

/*-----
Structure Declarations
-----*/

```

GET_SENSOR_STATE(SENSOR_NUMBER)

qt_measure_data is a variable of a library defined data structure qt_touch_lib_measure_data_t. In the above macro, we intend to get the touch status of a particular sensor and hence, the qt_touch_status[] consists of the information desired. As discussed earlier, qt_touch_status[] in itself is a structure that returns status of sensors and positions/angles of the slider/rotor.

Therefore the macro qt_measure_data.qt_touch_status.sensor_status[...] returns 1 if the particular sensor is in detect and returns 0 if it is not touched.

By checking the condition *if(GET_SENSOR_STATE(SENSOR_NUMBER))*, we know if a particular sensor has been touched. SENSOR_NUMBER here is the Sensor ID defined in the wizard. Accordingly, an action can be performed.


GET_ROTOR_SLIDER_POSITION(SENSOR_NUMBER)

It is defined as qt_touch_status.rotor_slider_values[...] returns the position of the slider sensor or the angle of the rotor slider.

The SENSOR_NUMBER here is not the same as the sensor ID used in the macro GET_SENSOR_STATE. This sensor number is assigned only to Rotors/Sliders in the order in which they are defined. The sensor_number in this case is 0 for a rotor and 1 for a slider since the Slider was defined after the Rotor.

SENSOR	SENSOR ID	SENSOR_NUMBER for ROTOR_SLIDER_VALUES
Button	0	--
Rotor	1	0
Slider	2	1

Therefore, a code as shown below is used to determine the sensors in detect and get the position or angle values on a scale of 0-255.



```
touch.c main.c Start Page
main.for for(;;)
/* Initialize Touch sensors */
touch_init();

/* loop forever */
for(;;)
{
    touch_measure();

    /* Time Non-critical host application code goes here */

    if (GET_SENSOR_STATE(0))
    {
        printf ("Button pressed");
    }
    if (GET_SENSOR_STATE(1))
    {
        rotor_value = GET_ROTOR_SLIDER_POSITION(0);
        printf ("Rotor reads %i\n",rotor_value);
    }
    if (GET_SENSOR_STATE(2))
    {
        slider_value = GET_ROTOR_SLIDER_POSITION(1);
        printf ("Slider reads %i\n",slider_value);
    }
}
}
```